

**Marathon Sensors Inc.
VersaPro Oxygen Monitor
Installation and Operation Handbook**



***Marathon
Sensors Inc.***

COPYRIGHT © 2000
MARATHON SENSORS INC

Marathon Sensors Inc.

Part # F200059

Revision 1.00 March 15, 2002
Revision 2.00 October 31, 2002
Revision 2.01 February 20, 2003
Revision 2.02 July 30, 2003
Revision 2.03 August 8, 2003
Revision 2.04 August 28, 2003
Revision 2.05 November 25, 2003

COPYRIGHT © 2003
MARATHON SENSORS INC.
3100 East Kemper Road, Cincinnati, Ohio 45241
1-800-547-1055 (513) 772-1000 FAX: (513) 326-7090

All trademarks used in this publication are duly marked and the sole property of their respective owners. No attempt at trademark or copyright infringement is intended or implied.

Windows is a registered trademark of Microsoft, Inc.
HyperTerminal is a registered trademark of Hilgraeve, Inc.

Marathon Sensors makes no warranties express or implied beyond the written warranty presented at initial purchase. Marathon Sensors Inc. is not responsible for any product, process, damage or injury incurred while using this equipment. Marathon Sensors makes no representations or warranties with respect to the contents hereof and specifically disclaims any warranties of merchantability or fitness for any particular application or purpose.

Table of Contents

SAFETY AND ENVIRONMENT INFORMATION 1

 SERVICE AND REPAIR 1

INSTALLATION SAFETY REQUIREMENTS 1

 SAFETY SYMBOL 1

 PERSONNEL 2

 ENCLOSURE OF LIVE PARTS 2

 LIVE SENSORS 2

 WIRING 2

 POWER ISOLATION 2

 EARTH LEAKAGE CURRENT 3

 OVER CURRENT PROTECTION 3

 VOLTAGE RATING 3

 CONDUCTIVE POLLUTION 3

 OVER-TEMPERATURE PROTECTION 4

 GROUNDING OF THE TEMPERATURE SENSOR SHIELD 4

 INSTALLATION REQUIREMENTS FOR EMC 4

 ROUTING OF WIRES 5

VERSAPRO FEATURES 6

INSTALLATION 6

 PANEL WIRING 7

 MOUNTING 8

PROCESS CONTROL OPTIONS 9

ALARMS 9

 PROCESS ALARMS 10

OFF 10

Full Scale HI 11

Full Scale LO 11

Fault 11

Probe 11

 ALARM ACTION 11

 ALARM DELAY TIMES 11

 HARDWARE FAULT ALARMS 12

 DISPLAY LIMITS 12

FRONT PANEL OPERATION 12

 SETUP KEY 14

 DUAL KEY FUNCTIONS 23

Starting Probe Tests 23

Monitor Mode 23

PROBE IMPEDANCE TEST 23

 WHY MEASURE SENSOR IMPEDANCE? 25

PROBE VERIFICATION 25

SCALING ANALOG INPUTS 28

Linear A example 28

Marathon Sensors Inc.

KEYBOARD FUNCTION DURING INPUT SLOPE.....	28
SCALING ANALOG OUTPUTS	28
CALIBRATION	29
CALIBRATION DISPLAYS AND KEYBOARD OPERATION	30
<i>Adjustment Sensitivity</i>	31
PREPARING FOR INPUT CALIBRATION.....	31
CALIBRATION OF THE THERMOCOUPLE INPUT.....	31
CALIBRATION OF THE PROBE MILLIVOLT INPUT	32
CALIBRATION OF THE ANALOG OUTPUT CHANNELS	33
PROCESS CALCULATIONS	34
OXYGEN PROCESS CONTROL.....	34
VERSAPRO MONITOR MODE.....	35
PREPARE OF THE DOWNLOAD	35
HOW TO CONNECT	35
START THE DOWNLOAD.....	36
WHAT IF AN ERROR OCCURS.....	39
TECHNICAL SPECIFICATION	41
ENVIRONMENTAL RATINGS	41
EQUIPMENT RATINGS	41
GENERAL	41
ELECTRICAL SAFETY (APPROVAL PENDING)	42
ELECTROMAGNETIC COMPATIBILITY	42

Safety and Environment Information

Please read this section carefully before installing the controller

This instrument is intended for industrial applications used in conjunction with Marathon Sensors zirconia oxygen sensors and standard thermocouple types. It is assumed that any installation meets either CE standards for industrial safety or NEC standard wiring practices. Failure to observe these standards or the installation instructions in this manual may degrade the safety or electrical noise protection provided by this instrument. It is the installer's responsibility to ensure the safety and electrical noise compatibility of any installation.

Service and repair

This controller has user replaceable fuses but no other user serviceable parts. The fuses are located at the rear of the power board.

Fuse Location	Marathon P/N	Mfg	Mfg P/N
Main AC Power	MFU-3.13PCTT	Wickmann	382 1315 041
FWD Control	MFU-1.0PCTT	Wickmann	382 1100 041
REV Control	MFU-1.0PCTT	Wickmann	382 1100 041
Alarm 1	MFU-1.0PCTT	Wickmann	382 1100 041
Alarm 2	MFU-1.0PCTT	Wickmann	382 1100 041

Contact your Marathon Sensors Service (800-547-1055) for repairs or spares.

Caution: Charged capacitors

Before removing an instrument from its case, disconnect the supply and wait at least two minutes to allow capacitors to discharge. Failure to observe this precaution will expose capacitors that may be charged with hazardous voltages. In any case, avoid touching the exposed electronics of an instrument when withdrawing it from the case.

Electrostatic Discharge (ESD) Precautions

When the controller is removed from its case, some of the exposed electronic components are vulnerable to damage by electrostatic discharge. Anyone who is not probably ground using an ESD wrist strap or in contact with a ground while handling the controller may damage exposed electronic components.

Installation Safety Requirements

Safety Symbol

Various symbols are used on the instrument, they have the following meaning:



Caution, (refer to the accompanying documents)



Functional earth (ground) terminal

The functional earth connection is required for safety ground and to ground RFI filters.

Personnel

Installation must be carried out by qualified personnel.

Enclosure of live parts

To prevent hands or metal tools touching parts that may be electrically live, the controller should be installed in an enclosure. The contacts on the rear of the instrument case or finger save but it is still possible for loose wiring, or metal objects to come in contact with live terminal connections. It is recommended that power be removed from the instrument connections before they are disconnected. However, instrument's power connector can be removed with power applied. Care should be taken that the connector does not come in contact with any grounded object.

Live sensors

The dc inputs, dc logic, and dc outputs are all electrically isolated from chassis ground. If the temperature sensor is connected directly to an electrical heating element then the inputs will also be live. The controller is designed to operate under these conditions. However you must ensure that this will not damage other equipment connected to these inputs and that service personnel do not touch connections to these terminals while they are live. With a live sensor, all cables, connectors and switches for connecting the sensor and non-isolated inputs and outputs must be mains rated.

Wiring

It is important to connect the controller in accordance with the wiring data given in this handbook. Take particular care not to connect AC supplies to the low voltage sensor input or other low level inputs and outputs. Only use copper conductors for connections (except thermocouple inputs) and ensure that the wiring for installations comply with all local wiring regulations. For example, in the UK, use the latest version of the wiring regulations, BS7671. In the USA use NEC Class 1 wiring methods.

Power Isolation

The installation must include a power isolating switch or circuit breaker. This device should be in close proximity to the control actuator, and within easy reach of the operator. There is no means of disconnecting power from the instrument other than removing the connectors from the rear of the instrument. It is recommended that

additional power disconnects are provided in the installation to remove power from these connectors as well.

Earth leakage current

Due to RFI Filtering there is an earth leakage current of less than 0.5mA. This may affect the installation of multiple controllers protected by Ground Fault Detector, (GFD) type circuit breakers.

Over Current protection

The instrument has an internal 3.15 Amp fuse (P/N MFU-3.15PCTT) for instrument power and 1 Amp fuses (P/N MFU-1.0PCTT) for the control contacts and alarms. It is recommended that additional protection against excess currents be used for loads exceeding this rating. Fusing and interposing relays should be added to the control circuit if high current or large inductive loads are used.

Voltage rating

The maximum continuous voltage applied between any of the following terminals must not exceed 250VAC:

- line or neutral to any other connection;
- relay output to logic, dc or sensor connections;
- any connection to ground.

The controller should not be wired to a three phase supply with an unearthed star connection. Under fault conditions in this supply could rise above 264VAC with respect to ground and the product would not be safe.

Voltage transients across the power supply connections, and between the power supply and ground, must not exceed 2.5kV. Where occasional voltage transients over 2.5kV are expected or measured, the power installation to both the instrument supply and load circuits should include a transient limiting device.

These units will typically include gas discharge tubes, metal oxide varistors, and constant voltage transformers help suppress voltage transients on the supply line due to lightning strikes or inductive load switching. Devices are available in a range of energy ratings and should be selected to suit conditions at the installation.

Conductive pollution

Electrically conductive pollution must be excluded from the cabinet in which the controller is mounted. For example, carbon dust is a form of electrically conductive pollution. To secure a suitable atmosphere in conditions of conductive pollution, fit

an air filter to the air intake of the cabinet. Where condensation is likely, for example at low temperatures, include a thermostatically controlled heater in the cabinet.

Over-temperature protection

When designing any control system it is essential to consider what will happen if any part of the system should fail. In temperature control applications the primary danger is that the heating will remain constantly on. Apart from scrapping the product, this could damage any process machinery being controlled, or even cause a fire.

Reasons why the heating might remain constantly on include:

- the temperature sensor becoming detached from the process;
- thermocouple wiring becoming a short circuit;
- the controller failing with its heating output constantly on;
- an external valve or contactor sticking in the heating condition;
- the controller setpoint set too high.

Where damage or injury is possible, we recommend fitting a separate over-temperature protection unit. Factory Mutual requires that any over temperature device use an independent temperature sensor isolated from the heating circuit.

Please note that the alarm relays within the controller will not give protection under all failure conditions. This instrument is not suited for over temperature protection and should not be used as a safety device.

Grounding of the temperature sensor shield

In some installations it is common practice to replace the temperature sensor while the controller is still powered up. Under these conditions, as additional protection against electric shock, we recommend that the shield of the temperature sensor be grounded at one end of the wire. Do not rely on grounding through the framework of the machine.

Installation requirements for EMC

To ensure compliance with European EMC directives certain installation precautions are necessary as follows:

- When using relay outputs it may be necessary to fit a filter suitable for suppressing the emissions. The filter requirements will depend on the type of load. For typical applications such as Schaffner FN321 or FN612 line filters or equivalents.

- If the unit is used in table top equipment which is plugged into a standard power socket, it is likely that compliance to the commercial and light industrial emissions standard is required. In this case, to meet the conducted emissions requirement, a suitable mains filter should be installed. Recommended filters would be Schaffner types FN321 and FN612 or equivalents.

Routing of wires

To minimize the pick-up of electrical noise, the wiring for low voltage dc and particularly the sensor input should be routed away from high-current power cables. Do not run signal cables in the same conduit or wire trays with AC power wiring. Where it is impractical to do this, use shielded cables with the shield grounded at one end.

VersaPro Features

The VersaPro is a single loop process controller / monitor has the following capabilities:

- Two channel 24 bit Sigma-Delta ADC for thermocouple, probe millivolt, with cold junction compensation.
- Two (2) Form A alarm contacts (threshold limits in monitor only).
- Internal relay for oxygen sensor verification.
- Internal relay for sensor impedance testing.
- Serial EEPROM stores setup and calibration values.
- Two (2) 4-20 milliamp outputs for control or chart recorder.
- Sixteen character LCD with two four digit LED segment displays.
- RS 485 serial communication port for either MSI protocol or Modus.


Installation

The VersaPro instrument is designed for up to 1/8" panel mounting in a DIN standard opening of 3.62" square (adapter panels available by special order). Required rear clearance is 7" to allow for wiring.

As with all solid state equipment, the controller should be located away from excessive heat, humidity, and vibration. Since the unit uses LED and LCD display devices, it should also be located so that direct sunlight will not interfere with the display's visibility. The instrument requires 120/240 VAC 50/60 Hz and should not be on the same circuit with other noise-producing equipment such as induction machines, large electrical motors, etc. Signal wiring must be run separate from control wiring. It is suggested that signal wiring at the rear terminals of the instrument be routed in one direction (up or down) while the AC power wires are routed in the opposite direction.

The following figure shows the rear terminals locations on the rear of the VersaPro.

Figure 1 VersaPro Rear Panel



Panel Wiring

The following diagram shows a typical wiring schematic for the monitor. Make sure that signal wiring is not run with power wiring in the same wire tray or conduit.




Figure 2 Panel Wiring

Mounting

To mount the instrument in a control panel, a hole must be cut 3.62" square in the necessary location on the panel. The following procedure should be followed to mount the VersaPro in the panel.

- 1) Insert the unit into previously cut out 3.62" square hole in panel.
- 2) While supporting unit, insert one clamping bracket into the groove on the bottom of unit, and then install the 6-32 set screw.
- 3) Repeat step 2 for the top of the unit.
- 4) With a HEX KEY wrench, alternately tighten the screw on either side of instrument to a torque of six in.-lbs. Insure rigidity of mounting. **DO NOT OVER TIGHTEN.** This can wrap the instrument enclosure and make removal difficult.

To remove the instrument from the panel, reverse the above procedures.

Process Control Options

The Versapro can be configured to perform a number of specific control functions. The following table outlines the available process functions for the oxygen controller / monitor.

Table 1 Instrument Monitoring Options

Function	Description
Oxygen	Uses the millivolt and temperature signals from a zirconia sensor to calculate oxygen concentrations and control to an oxygen set point.

Alarms

The instrument has two types of alarms, process alarms and diagnostic alarms. If an alarm has been selected and conditions are such that the alarm becomes active, the instrument will display this condition on the center LCD display. The alarms are numbered as Alarm 1 and Alarm 2. The various displays for active alarm conditions would be displayed as shown below. N indicates the position of the alarm number, 1 or 2.

ALARM DISPLAY	CONDITION	ACTION
FULL HI N	Alarm contact assigned	Full Scale High, Contact automatically resets unless latched.
FULL LOW N	Alarm contact assigned	Full Scale Low, Contact automatically resets unless latched.
PROBE IMPEDANCE	Alarm contact assigned	Probe Impedance High, Contact automatically resets unless latched.
VERIFICATION	Alarm contact assigned	Probe Verification out of tolerance, Contact automatically resets unless latched.
LLLL	Display only	Displays process value within display range or exponent setting
HHHH	Display only	Displays process value within display range

Marathon Sensors Inc.

		or exponent setting
FLASH CSUM	Alarm contact assigned	Reset instrument power. Return to Marathon if error does not clear.
EEPROM CSUM	Alarm contact assigned	Reset instrument power. Return to Marathon if error does not clear.
KEYBOARD	Alarm contact assigned	Reset instrument power. Do not push any keys while instrument is powered on. Return to Marathon if error does not clear.
FLASH ERASE	Alarm contact assigned	Programming error, Reset instrument power, attempt reload.
FLASH / EE SIZE	Alarm contact assigned	Programming error, Reset instrument power, attempt reload.
ADC FAULT	Alarm contact assigned	Reset instrument power. Return to Marathon if error does not clear.
TEMP OPEN	Alarm contact assigned	Check thermocouple for open condition or loose connection.
MV OPEN	Alarm contact assigned	Check probe millivolt signal for open condition or loose connection. This signal can only be tested if the probe temperature is above 1300°F and exposed to process gas.

Process Alarms

The process alarms can be setup to activate either or both of the two alarm contacts provide on the VersaPro. Nine user selectable modes are available.

OFF

Disables the alarm function and the alarm contacts.

Full Scale HI

An alarm is generated any time the process value goes above the Full Scale HI alarm value. This alarm is reset if the process falls below the alarm value or acknowledgement from the front panel or through the event input (if configured).

Full Scale LO

An alarm is generated any time the process value drops below the Full Scale LO alarm value. The alarm will arm once the process is measured above the alarm value. This alarm is reset with an acknowledgement from the front panel or through the event input (if configured).

Fault

An alarm is generated any time an open input occurs on either the T/C or MV inputs. Both inputs are pull up to a maximum value if no input is connected or if the input fails in an open circuit mode. An open T/C input fault is ignored for the Linear configuration. The center display will indicate which of these conditions has caused the alarm. The alarm process will also become active if any of the listed hardware faults occur. The center display will indicate which of these conditions has caused the alarm. A fault alarm can not be cleared unless the condition causing the alarm is resolved.

Probe

An alarm is generated any time the probe exceeds the maximum probe impedance setting, or the verification test tolerance. All of the probe values and limits are configured in the Probe Menu. The center display will indicate which of these conditions has caused the alarm.

Alarm Action

Each alarm can be configured to operate in several different modes. Each alarm can be configured as a reverse (normally closed) contact. This mode is usually used for failsafe alarms that will open during an alarm condition, fault, or power failure. Each alarm can also be configured as a direct (normally open) contact that closes when an alarm condition occurs. In both cases the alarm will automatically clear if the alarm condition is resolved.

Each alarm can also be configured for either reverse or direct latched conditions. In this mode the alarm contact will remain active until an acknowledgement is received through the event port or by pressing the ENTER key.

Alarm Delay Times

Each alarm can have delay ON, delay OFF, or both delays applied. Delays can be applied in increments of a second, up to a maximum of 250 seconds. ON delays are

helpful if a known upset in the process can be ignored. This avoids nuisance alarms but still maintains an active alarm if the alarm condition persists following the delay. OFF delays will hold the alarm contact active for a determined period of time once the alarm condition has cleared. This can be helpful as an interlock to other process functions that may have to recover following an alarm condition.

Hardware Fault Alarms

A fault alarm is shown on the instrument's center display when a fault is detected in the internal hardware during power up. These alarms included:

FLASH CSUM	A fault has been detected in the Flash memory.
EEPROM CSUM	A fault has been detected in the EEPROM.
KEYBOARD	A key is stuck or was held down during power up.
FLASH ERASE	This error may occur during instrument programming. The Flash memory may be faulty. Retry programming, make sure the communications link to the instrument is working properly.
FLASH / EE SIZE	This error may occur during instrument programming. The Flash memory may be faulty. Retry programming, make sure the communications link to the instrument is working properly.
ADC FAULT	The analog / digital converter has failed to initialize or failed self calibration.

If either alarm contact is configured for a fault this alarm will engage if any of the above faults occur. The LCD display will indicate the fault condition. A fault can not be acknowledged. It most clear on power up or after the instrument memory has been reconfigured. Contact the Marathon Sensors Service department if any of the above faults occur and will not clear following a power reset.

Display Limits

The front panel display will show 0000 if the process value is below the display resolution, or 'hhhh' if the process value is above the display resolution. It may be necessary to adjust the oxygen exponent and/or the oxygen decimal point settings if these symbols occur.

Front Panel Operation

The instrument has a display/keyboard assembly. This assembly has a 2 x 4 keyboard group, two groups of four LED seven segment displays (upper and lower), and a single line sixteen character LCD display.




Figure 3 VersaPro Display

The LEDs to either side of the LED segment arrays light when the corresponding function is active.

- COMM flashes when the instrument is properly interrogated over the RS485 port.
- PWR is hard wired to the instrument 5VDC supply
- AUTO is lit when the instrument is controlling to a set point (controller option)
- REM is lit when the instrument is controlling to a remote set point (controller option)

The upper display indicates the process value or the Setup Menu Heading when the SETUP key has been pressed.

The center display will indicate what scaling is being used for the oxygen measurement. In figure 2 the instrument is indicating that % oxygen is being measured. This measurement range can be changed to indicate parts per million (ppm) or other measurement ranges based on the oxygen exponent setting in the Setup Calc(ulation) menu. The exponent setting has a range of 0 to E-31. Other possible displays could be; Oxygen E-12, Oxygen E-20, etc.

The center display also shows the parameter name in Setup mode or flashes a fault or alarm message if any are active.

The lower display shows the instrument set point if the controller is in automatic or remote mode. The display will switch to control output level when the instrument is changed to manual. The monitor option will display the probe temperature by default. The lower display can be configured to display other parameters based on the instrument option.

Setup Key

The instrument can be placed in setup mode by pressing and holding the SETUP key for 5 seconds. The upper display initially shows the first setup menu while the center and lower displays are blank. At this level you can select different menus by pressing the RIGHT or LEFT arrow keys. The upper display will change accordingly.

You can enter a menu by pressing the ENTER key when the desired menu heading is being displayed. Pressing the arrow keys can change menu parameters. Value changes can be saved or the next parameter can be selected by pressing the ENTER key. The menu parameters will continue to cycle through the display as long as the ENTER key is pressed. A new menu can be select only when the menu heading is displayed. You can exit from the Setup mode by pressing the SETUP key at any time.


The following tables outline the Setup menus available in the VersaPro Controller and Monitor when the operator presses the SETUP key.

Table 2 Setup Menus

Setup Menu Heading	Description
Ctrl	Process functions
Inpt	Thermocouple type and Millivolt setup
Calc	Oxygen exponent setting
Prob	Probe tests and verification parameters
Aout	Analog output selection and parameters
ALr	Alarm contact configurations
Evnt	Digital Input function selection
Info	General information displays
CaL	Input / Output calibration

You have to press the SETUP key for five seconds to activate the setup mode. If a lock level of 1 or higher is set, you may also have to enter a password to proceed. Initially when the setup mode is activated, the LCD display will show the first menu heading, the upper and lower LED displays are blank. Page to the next Menu heading by pressing the RIGHT or LEFT arrow keys. The menu headings will continue to wrap around as the RIGHT or LEFT arrow keys are pressed. Pressing

the SETUP key at any point while in the Setup Menus will return the display to the normal process display. See figure 3.



The displayed menu is selected by pressing the ENTER key. The first parameter name in the selected menu list will appear in the center display. The upper LED group continues to display the menu name, the center display shows the parameter name, and the lower LED group shows the parameter value. A flashing cursor in the lower LED display indicates which digit can change if the parameter value is numeric.

The UP or DOWN arrows increase or decrease the digit value. The RIGHT or LEFT arrow keys move the cursor to the right or left digit. No wrap-around is provided for the cursor.

If the parameter has a table of choices such as thermocouple types, the various selections can be displayed by pressing the UP or DOWN arrows. No digit flashes in parameter displays that have a choice selection. In either case, the selection is set when the ENTER key is pressed and the display advances to the next parameter.

In the example shown above, the selected menu is Control (Ctrl), the selected parameter is Control Type, and the displayed parameter value is O2. This is one of several process types that are available. Different control selections can be made by pressing the UP or DOWN arrow keys.

Pressing the SETUP key at any time escapes from the menu display and returns to the normal process display. You can only select another menu heading when the display is at a menu heading.

The following figures and tables outline the menu options and parameters under the Setup key. **Default settings are shown in BOLD.**




Figure 4 Setup Menu Tree

Marathon Sensors Inc.

Table 3 Control Menu (Ctrl)

Parameter Name	Options / Default	Range	Description
PROCESS SOURCE	O2	Display range: 0.000 to 9999	Control type only available on instrument's specific configuration. This selection controls what other parameters will be available.
SENSOR OPEN	ZERO HOLD		0% OUTPUT sets the control output to 0 if a thermocouple break and/or an open mV input are detected. HOLD holds the output to the last averaged output prior to a break and/or open input.
CONTROL MODE	NON		Indicates that the instrument is configured for monitor only.

Table 4 Input Menu (InPt)

Parameter Name	Options / Default	Range	Description
TC TYPE	B, E, J, K, N, R, S, T		See Input calibration for thermocouple ranges.
COLD JUNC APPLY	YES or NO		Applies the cold junction correction or not when a thermocouple type is selected.
IN A OFFSET	No effect	0	No effect in oxygen monitor.
IN A SLOPE	No effect	1	No effect in oxygen monitor.
TEMP SCALE	F OR C		Sets temperature scale.
TC FILTER	SECONDS 1000	0 – 9999	Temperature filter time constant. Filters the temperature value with a moving average time window. Higher numbers decrease average time.
IN B OFFSET	No effect	0	No effect in oxygen monitor.
IN B SLOPE	No effect	1	No effect in oxygen monitor.

Marathon Sensors Inc.

MV FILTER	SECONDS 1000	0 – 9999	Millivolt filter time constant. Filters the millivolt reading with a moving average time window. Higher numbers decrease average time.
-----------	------------------------	----------	--

Table 5 Calculation Menu (CALC)

Parameter Name	Options / Default	Range	Description
OXYGEN EXPONENT	POWER OF TEN 2	0 – 31	2 = %, 6 = ppm, 9 = ppb Available in O2 only. The negative value of the exponent is assumed. (This parameter is also shown in control menu)
LOWER DISPLAY	TENP		Monitor always shows probe temperature (TENP).

Table 6 Probe Setup Menu (PrOb)

Parameter Name	Options / Default	Range	Description
PROBE TEST	NONE RES VER BOTH		No test (NONE), Impedance (RES), Verification (VER), or BOTH impedance and verification can be selected.
START TEST	YES/NO		If probe test interval is 0, then test only runs once. If probe test interval is set then test run continuously from start point and at each interval time. Test stops when changed back to NO. Probe temp must be \geq the minimum probe temperature setting.
TEST INTERVAL	HRS.TENTHS 00.0	0 – 99.9	Sets time interval between automatic probe tests, 0 disables automatic testing.
PROBE IMP LIMIT	KOHMS 20	10 – 100	Sets maximum impedance for Probe alarm
IMP RECVRY TIME	SECONDS 30	0 – 250	Sets maximum Probe recovery time, timer cut

Marathon Sensors Inc.

			short if probe recovers faster. The Probe alarm is set if the probe signal does not recover while this timer is active.
VERIFY DELAY	SECONDS 30	0 – 999	Initial verification delay. O2 function only. This delay allows time for the verification gas to flow to the tip of the probe.
VERIFY AVG TIME	SECONDS 30	0 – 999	Verification sampling time.
VERIFY RECOVERY	SECONDS 30	0 – 999	Recovery time for probe following verification test. The PROBE alarm is set if the probe signal does not recover before this timer expires.
VERIFY STANDARD	% OXYGEN 3.0	0 – 25.0	Percent of O2 used as verification gas.
VERIFY TOLERANCE	% OXYGEN 0.5	0 – 25.0	Tolerance (O2%) for acceptable measurement. Specified in the same units as the displayed O2. O2 function only. The PROBE alarm is set if the oxygen level measured during verification exceeds this tolerance.
MIN PROBE TEMP	1400 F	1100° – 2000° F 590° – 1090° C	Minimum temperature for probe impedance and verification tests.

Table 7 Analog Output Menu (AOut)

Parameter Name	Units or Options	Range	Description
ANALOG 1 UNIT	O2 , TENP	4 to 20mA output.	O2 – retransmits Oxygen if oxygen is selected as process source. TENP - probe temperature when oxygen is selected as process source and a thermocouple type is selected.
ANALOG 1 OFFSET	Offset for	-9.99 to 40.00	This is the minimum value

Marathon Sensors Inc.

	selected process value or percent output. 0.00	-999 to 9999 for temperature	of the process associated with the 4mA output. The magnitude of this number is based on the display resolution.
ANALOG 1 RANGE	Span scaling for selected process value or percent output. 20.9	-9.99 to 99.99 for O2 -999 to 9999 for Temp	This is the maximum value of the process associated with the 20mA output. The magnitude of this number is based on the display resolution.
ANALOG 2 UNIT	O2, TENP ,		Same as Analog 1
ANALOG 2 OFFSET	Offset for selected process value or percent output. 0		Same as Analog 1
ANALOG 2 RANGE	Span scaling for selected process value or percent output. 3000		Same as Analog 1

Table 8 Alarm Menu (ALr)

Parameter Name	Units or Options	Range	Description
ALARM 1 TYPE	OFF FSHI, FSLO FALT PROB		OFF disables alarm contact. FSHI - Full Scale HI , active when process is above ALARM 1 VALUE. FSLO - Full Scale LO , active when process is below ALARM 1 VALUE. Falt – Fault , open inputs for mV, thermocouple or hardware fault. Prob – Probe , active if impedance or verification tests are out of range.
ALARM 1 VALUE	0		Trigger set point value
ALARM 1 ACTION	REV, LREV, DIR , LDIR		REV = Reverse (N.C.) can be acknowledged even if the condition still exists. LREV = Latched Reverse (N.C.) can not be

Marathon Sensors Inc.

			acknowledged if the condition still exists. DIR = Direct (N.O.) can be acknowledged even if the condition still exists. LDIR = Latched Direct (N.C.) can not be acknowledged if the condition still exists.
ALRM 1 TM ON DLY	0 – 250 SECONDS		Delay ON time for ALARM1
ALRM 1 TMOFF DLY	0 – 250 SECONDS		Delay OFF time for ALARM1
ALARM 2 TYPE	Same as ALARM 1 TYPE OFF	OFF	Same as ALARM 1 TYPE
ALARM 2 VALUE	0		Trigger set point value
ALARM 2 ACTION	DIR		Same as ALARM 1 ACTION
ALRM 2 TM ON DLY	0 – 250 SECONDS		Delay ON time for ALARM2
ALRM 2 TMOFF DLY	0 – 250 SECONDS		Delay OFF time for ALARM2

Table 9 Info Menu (I nFO)

Parameter Name	Units or Options	Range	Description
MILLIVOLT TEMP IN	MILLIVOLTS	-10-100	Displays direct mV of Temperature input
MILLIVOLT PROB IN	MILLIVOLTS	0-2000	Displays direct mV reading of probe input
COLD JUNCTION	DEG (F OR C)	0 – 60°C	Displays actual cold junction temperature
PROB IMPEDANCE	Kohms	0 – 100	Displays last probe impedance value.
IMP RECVRY TIME	SECONDS	0 – 250	Displays last impedance recovery time.
VERIFY READING	% OXYGEN	0 – 025.0	Displays last verification reading. O2 configuration only.
NEXT TEST	Hours.tenths		Time to next probe test, shows 00.0 if test automatic test is disabled.
FIRMWARE REV	Version number		

Table 10 Calibration Menu

Parameter Name	Units or Options	Range	Description
CAL INPUT	NO / YES		Default to NO, must be changed to YES to enter input calibration routine.
TC ZERO			Changes calibration value for thermocouple zero
TC SPAN			Changes calibration value for thermocouple span
CJ OFFSET (CAL IN)		0 – 60° C 0 – 140° F	Sets the cold junction offset depending on the temperature range selected
CAL OUTPUT	NO / YES		Default to NO, must be changed to YES to enter output calibration routine.
OUTPUT 1 MIN (CAL OUTPUT)			Sets signal level for the minimum mA output.
OUTPUT 1 SPAN (CAL OUTPUT)			Sets signal level for the maximum mA output.
OUTPUT 2 MIN (CAL OUTPUT)			Sets signal level for the minimum mA output.
OUTPUT 2 SPAN (CAL OUTPUT)			Sets signal level for the maximum mA output.

Pressing the Setup key once at any point in the Setup menu will return the instrument to the normal process display.

Dual Key Functions

The VersaPro has three dual key functions as defined below:

ENTER / RIGHT arrow	Initiates probe test sequence
ENTER / REM	Monitor Mode

Starting Probe Tests

Pressing the ENTER / RIGHT arrow keys simultaneously will start the probe tests if a probe test function has been selected in the Probe Setup Menu, parameter Probe Test, and the probe temperature is above the minimum probe temperature parameter in the same menu.

If there is a value other than 0 entered in the Probe Test Interval parameter the probe test will be performed after the selected interval time has elapsed from the time the test was manually started. If the interval time is set to 0 then no additional tests will be performed until the next manual start. Starting the test through this dual key function is the same as if the Start Test parameter in the Probe menu had been changed from NO to YES.

Monitor Mode

Monitor Mode is used by factory personnel only. Return to operate mode by cycling power or sending the appropriate command word to the instrument.

Probe Impedance Test

The probe impedance test is performed by measuring the open circuit voltage of the probe, applying a known shunt resistor across it and measuring the shunted voltage output. The value of the shunt resistor is 10kohm for oxygen sensors.

To run a probe impedance test it is necessary to setup the probe testing parameter in the SETUP Probe Menu. Please refer to Probe parameters table for an explanation of these setup parameters. It is necessary to have the impedance (RES) test or both (BOTH) selected at the PROBE TEST parameter in order to run the impedance test. You may choose to accept the defaults for the other parameters in this menu or change them to suit your applications. It is necessary that the sensor be above the MIN PROBE TEMP parameter setting for this test to run. It is also necessary for the probe to be measuring a stable process gas during this test.

There are two ways to start this test. From the Probe Setup menu at the START TEST parameter, you can change this parameter from NO to YES and then press the SETUP key. The instrument will display the test name and sequence number on the

Marathon Sensors Inc.

front display. The LCD display will indicate “IMPEDANCE TEST” while the lower LED display will show the test sequence number as listed in the following table.

It is also possible to start the test in the process display mode by pressing the ENTER and RIGHT ARROW keys at the same time if an interval time has been entered. The test can be stopped by returning to the START TEST parameter and changing YES to NO and then pressing ENTER.

If the TEST INTERVAL parameter has a number other than 00.0 then the test will continue to run each time the test interval timer counts down to 0. The test interval function can be stopped by setting the interval timer to 00.0.

The following table explains the various operations of the impedance test.

Table 11 Probe Impedance Sequence

Sequence #	Description
1	Inhibit process variable calculations. Freeze all process controls and outputs.
	Freeze alarms at last state except clear any previous probe test failure alarm.
	Store present probe millivolt reading
	Apply shunt resistor across probe
2	Wait for impedance test timer, fixed time of 30 seconds
	Compute impedance of probe and remove shunt resistor. Save measured impedance as PROBE IMPEDANCE in INFO menu.
	If impedance is greater than PROBE IMP LIMIT then set probe test failure alarm.
3	Wait for probe to recover to >=99% of original millivolts.
	Evaluate actual recovery time to IMP RECVRY TIME
	If recovery time is greater than IMP RECVRY TIME then set probe test failure alarm.
	Store recovery time (or max value) as IMP RECVRY TIME in INFO menu
4	If verification is to be performed then go to step 1 of verification sequence
	Otherwise wait 30 seconds and resume normal operation of all instrument functions.

Why Measure Sensor Impedance?

It is important to track sensor impedance over a period of time to help determine the replacement schedule for the sensor. A high impedance (>50 KΩ) indicates that the electrode contact on the probe zirconia has deteriorate to a level that probably warrants replacement. High sensor impedance results in a lower signal output from the sensor and an eventual failure of the electrode connection on the process side of the zirconia ceramic. This deterioration is more of a factor in highly reducing atmospheres. In such applications, it may be necessary to check the impedance at least once a month. Under light reducing, annealing, or brazing operations, the impedance may not have to be check unless there is a question about the probe's performance.

A typical impedance for a new probe is less than 1 KΩ. As the probe starts to age the impedance will increase. Past 20 KOHM the sensor should be monitored more closely. Above 50 KΩ, the sensor should be replaced. If it is necessary to replace the sensor, remove it carefully, following the instructions supplied with the sensor. Do not discard a sensor with a high impedance. It may be possible to rebuild the sensor if the ceramic parts are intact. Contact Marathon Sensors, Inc. for information on rebuilding your sensor.

An impedance test can only be performed if the probe temperature is at or above 1300°F with stable atmosphere present. The instrument freezes all control functions and process signals during the test.

A 10KΩ resistor is shunted across the sensor output. The sensor impedance is calculated as:

$$R_x = [(E_o/E_s)-1]*R_s$$

Where R_x = sensor impedance, E_o = sensor's open circuit voltage, E_s = shunted sensor's voltage, and R_s = shunt resistor. The units of R_x are the same as R_s .

Probe Verification

Probe verification is performed by measuring the probe signal when a known calibration gas has been allowed to flood the sheath of the oxygen probe. A ¼" CPI compression fitting at the mounting hub of Marathon Sensors oxygen sensors is provided for the connection the verification gas. When a gas of known oxygen level is allowed to flow through this port, it floods the probe sheath and flows out and around the oxygen sensor. This method does not use the process as the basis for measurement nor does it have to assume that the process is stable, but the sensor does have to be above the MIN PROBE TEMP parameter found in the PROBE setup menu. This value is typically 1300°F or higher.

To run a probe verification test it is necessary setup the probe verification test parameters in the SETUP Probe Menu. Please refer to Probe parameters table for an explanation of these setup parameters. It is necessary to have the verification (VER) test or both (BOTH) selected at the PROBE TEST parameter in order to run the verification test. You may choose to accept the defaults for the other parameters in this menu or change them to suit your application. It is necessary that the sensor be above the MIN PROBE TEMP parameter setting for this test to run. It is not necessary for the probe to be measuring a stable process gas during this test.

There are two ways to start this test. From the Probe Setup menu at the START TEST parameter, you can change this parameter from NO to YES and then press the ENTER key. The instrument will exit the Setup mode and display the test name and sequence number on the front display. The LCD display will indicate “VERIFY TEST” while the lower LED display will show the test sequence number as listed in the following Table.

It is also possible to start the test in the process display mode by pressing the ENTER and RIGHT ARROW keys at the same time. The test can be stopped by returning to the START TEST parameter and changing YES to NO and then pressing ENTER.

If the TEST INTERVAL parameter has a number other than 00.0 then the test will continue to run each time the test interval timer counts down to 0. This test interval can be stopped by setting the interval timer to 00.0.

Readings are averaged to eliminate variations in measurement due to initial flow conditions. There are three operator inputs for verification time periods;

- TEST INTERVAL is an interval timer that sets the time between automatic verifications in hours and tenths. The verification can be manually initiating by pressing and holding the Enter key and then the Left Arrow key. Setting the test interval time to zero disables automatic testing.
- VERIFY DELAY TIME is the initial stabilization period in seconds.
- VERIFY AVG TIME is the measurement averaging time period in seconds.
- VERIFY RECOVERY is the time period in seconds that allows the probe to recover and return to the process level.

Two values allow the operator to set the actual value of the verification gas and the allowed tolerance for the measured comparison.

- VERIFY STANDARD is the oxygen level of the gas standard in percent oxygen.
- VERIFY TOLERANCE is the measurement tolerance specified in percent oxygen.
- MIN PROBE TEMP is the minimum probe temperature that must be met to allow the test to proceed.

Marathon Sensors Inc.

The following table outlines the actions the instrument takes at each sequence step.

Table 12 Probe Verification Sequence

Sequence #	Description
1	Inhibit process variable calculations. Freeze all process controls and outputs.
	Freeze alarms at last state except clear any previous probe test failure alarm.
	Close verification contact and wait the VERIFY DELAY time period.
2	Average oxygen readings from probe during the VERIFY AVE TIME period.
3	Release the verification contact and wait the VERIFY RECOVERY time period.
	Evaluate the averaged oxygen reading to the VERIFY STANDARD \pm VERIFY TOLERANCE. Set alarm fault if comparison fails.
	Save averaged verification reading as VERIFY READING in INFO menu.
4	Resume normal operation of all instrument functions.

The equation for the verification sequence is the standard percent oxygen equation:

$$\%O_2 = \frac{20.95}{e^{(E/0.0215 \cdot T_k)}}$$

Where:

E = probe millivolts, T_k = probe temperature in degrees Kelvin.

20.95 is the %O₂ in air.

Scaling Analog Inputs

If either input is set to Linear mode the displayed value for that input can be scaled to desired engineering units. This is helpful if the measured linear value has to be scaled and re-transmitted on one of two analog output channels.

Using the equation $y = mx + b$, where

Y is the desired engineering unit to be displayed

X is the linear millivolt value

M is the Slope of the y/x relationship

B is the y intercept

Linear A example

Let us use Input A as a linear input for a linear oxygen cell that outputs a 0mV to 53.2mV signal over a 0% to 100% oxygen range. Since both the signal output and the process minimum are both 0, the Input A offset will be 0. The slope can be calculated by dividing the maximum process value (100) by the maximum input level (53.2mV). This gives a slope value of 1.879. Since the slope parameter only has three digits, the actual number to be entered is 1.88. The decimal point has to be shifted twice to the left.

These scaling values will produce a process value of 100.0160% oxygen for a maximum sensor input of 53.2mV. The process display can be configured to display either 100 or 100.0. This process value can then be retransmitted to other control devices or a recorder. The control model of the Versapro will be able to control to a set point for the new process value.

Keyboard Function during Input Slope

The three left digits in the slope display can be changed from 0 to 9. The most significant digit position allows you to shift the decimal point by pressing the LEFT arrow key. The decimal point will loop from first digit to the third digit as the LEFT arrow key is pressed. The RIGHT arrow key moves the display cursor back to the numbered digits.

Scaling Analog Outputs

The analog outputs are scaled to simple offset and span values. For example if analog output 1 is to be scaled for a 0 to 100% oxygen value, the offset value would be 0 and the span value would be 100. This assumes that the process oxygen value is also scaled for percent oxygen where the oxygen exponent is set to 2.

For ppm values the analog output would be scaled to the display resolution of the process. For example, if the process display is 6.5 ppm, with a oxygen exponent of 6, the full scale display resolution would be any number between 000.0 and 999.9.

The analog output can be scaled to a reasonable range of 0 to 10, which would drive the 4 – 20mA output over a 0 to 10ppm range and the 6.5 ppm process value would result in an output of 14.4mA.

The same rules apply to analog output 2. The range of the offset and span numbers depends on the range of the process value that has been selected for either analog output.

Additional selections for Power Output and Program mode have fixed offset and span values. The power output offset and span values are fixed to the LOPO and HIPO values selected for the control outputs under the Setup Control menu.

The Program mode selection has a fixed offset of 0 and a fixed span of 4096. When this output mode is selected the analog output can only be changed by writing a value to either the DACV1 or DACV2 registers.

Calibration

There are two analog inputs, a cold junction compensation sensor, and two analog outputs on the VersaPro. The input level is determined by which terminals are used for the input signal. There are two pairs of input terminals: TB-B 1, 2 for the thermocouple (T/C) input and TB-B 3, 4 for the probe millivolt input.

The 4 – 20mA analog outputs are at TB-B 5, 6 and TB-B 7, 8.

The following is a brief description of input/output and its specifications.

- | | | | |
|----|----------------|-----------------|---|
| a) | T/C Input | Input range | -10 to +70 millivolts \pm 2 μ V |
| | | TC burnout | >full scale |
| b) | Probe mV Input | Input range | -50 to +2000 millivolts \pm .1 mV, linear |
| | | Input impedance | 40 megohm |
| | | Open input | >full scale |
| c) | Output 1 | Output range | 0 to 20 milliamps |
| | | Max. Load | 650 ohms |
| d) | Output 2 | Output range | 0 to 20 milliamps |
| | | Max. Load | 650 ohms |

Calibration Displays and Keyboard Operation

When entering the Calibration Menu, the operator has to answer one of two questions depending on which I/O functions have to be calibrated. If the CALIBRATION IN prompt is answered with a YES, then the parameters related to the thermocouple input, millivolt input, and cold junction are displayed. If this prompt is skipped by pressing the Enter key, then a second prompt, CALIBRATION OUT is displayed. If this prompt is answered with a YES, then the parameters relate to the analog outputs are displayed.

In the Calibration Menu the displays and front panel keys take on special assignments. The process display shows the value of the input being calibrated with a flashing digit. This flashing digit indicates the relative sensitivity of the arrow keys, as described following the key descriptions. The upper LED display indicates the zero or the span value is being modified. The lower LED display indicates the calibration factor that is changed for each I/O channel. The LCD display indicates the name of the parameter to be adjusted.

It is very important that the display is indicating the proper I/O parameter before making an adjustment or the wrong value will be changed.

Once the particular calibration mode is selected, the process values are displayed in the upper LED group. The following keys perform the described functions:

<u>Key</u>	<u>Function</u>
LEFT ARROW	Increases the adjustment sensitivity by moving the blinking cursor to the most sensitive position (far left position). A further press of the key loops the adjustment to the least sensitive position (far right position).
RIGHT ARROW	Decreases the adjustment sensitivity by moving the blinking cursor to the least sensitive position (far right position). A further press of the key loops the adjustment to the most sensitive position (far left position).
UP ARROW	Increases the digit indicated by the blinking cursor.
DOWN ARROW	Decreases the digit indicated by the blinking cursor.
SETPT	Resets the selected calibration factor to the theoretical preset.
ENTER	Cycles to next input value or saves the calibration changes.
SETUP	Exits the calibration mode.

Adjustment Sensitivity

The adjustment sensitivity works in the following manner. If the right most digit in the process display is flashing then each press of the up or down arrow key will change the displayed process value by a single calibration unit. If the left most digit is flashing then each press of the up or down arrow key will change the process value by a thousand calibration units. Likewise the middle digits will indicate sensitivities of a hundred and ten units respectively. The input value will usually change by an amount less than the calibration factor; however, by observation of the change, the sensitivity can be selected in order to allow the calibration factors to be adjusted more quickly. As the desired value is approached, less sensitive adjustments are required.

Preparing for Input Calibration

Make sure you have the correct thermocouple type selected on the instrument if you see a significant difference between the thermocouple input and the displayed temperature on the instrument.

Calibration of the Thermocouple Input

This calibration procedure assumes that a thermocouple type has been selected.

Calibration procedure:

1. Connect the input to be calibrated to a junction compensated calibrator (i.e. Biddle Instrument Co. Versa-Cal Calibrator) using the proper extension wire for the thermocouple type selected.
2. Activate the calibration mode by entering the SETUP menus, selecting the Calibration menu and changing Calibration IN - NO to YES.
3. Use the Enter key to select the TC ZERO mode.
4. Set the calibrator output to the recommended zero value in Table 17 for the thermocouple type selected.
5. Using the arrow keys, adjust the process value to equal the calibrator input.
6. Press the Enter key to select the TC SPAN mode.
7. Set the calibrator output to the recommended span value in the following table for the thermocouple type selected.
8. Using the arrow keys, adjust the process value to equal the calibrator output.

9. Repeat steps 3 through 8 by pressing the Enter key until no additional change is needed.

Table 13 Thermocouple Calibration Values

T/C type	Minimum Value °F (°C)	Maximum Value °F (°C)
B	800 (426)	3000 (1800)
E	-454 (-270)	1832 (1000)
J	32 (0)	1300 (900)
K	32 (0)	2300 (1200)
N	32 (0)	2300 (1200)
R	300 (150)	3000 (1800)
S	300 (150)	3000 (1800)
T	32 (0)	700 (350)

The usable ranges for the thermocouple types are shown in the following table . If it is desirable to have a higher accuracy over a specific operating range then the input should be calibrated over that range.

Table 14 Usable Thermocouple Range (°F)

T/C type	Minimum Value (°F)	Maximum Value (°F)
B	800	3270
E	-440	1830
J	-335	1400
K	-340	2505
N	-325	2395
R	300 *	3210
S	300 *	3210
T	-380	755

* Due to the extreme non-linearity of low level signals, using type R and S below 300° F is not recommended.

Calibration of the Probe Millivolt Input

Calibration procedure:

1. Connect terminals TB-B 3, 4 to an isolated, stable voltage source calibrator.
2. Set the calibrator output to zero or short TB-B 3, 4 together with a short piece of wire.

3. Activate the calibration mode by entering the SETUP menus, selecting the Calibration menu and changing Calibration IN - NO to YES.
4. Use the Enter key to select the MV ZERO mode.
5. Set the calibrator output to a zero millivolt output.
6. Using the arrow keys, adjust the process value to equal the calibrator input.
7. Press the Enter key to select the MV SPAN mode.
8. Set the calibrator output to the required millivolt span (2000mV maximum).
9. Using the arrow keys, adjust the process value to equal the calibrator output.
10. Repeat steps 4 through 9 by pressing the Enter key until no additional change is needed.

Calibration of the Analog Output Channels

The same calibration procedure can be used for either output channel.

Calibration procedure:

1. Connect terminals TB-B 5, 6 (or 7, 8) to a multimeter such as a Fluke 77. Select the milliamp measurement range and verify that the test leads are plugged into the milliamp jack and common on the multimeter.
2. Activate the calibration mode by entering the SETUP menu, selecting the Calibration menu (CAL), press the ENTER key until CAL OUTPUT - nO is displayed.
3. Change the nO prompt to YES using the UP arrow key.
4. Press the ENTER key to select the OUTPUT 1 MIN mode. In OUTPUT 2 is required, continue pressing the ENTER key until OUT 2 MIN is displayed.
5. Using the UP or DOWN arrow keys, adjust the flashing digit value. Press the RIGHT or LEFT arrow keys to select the adjustment sensitivity. Adjust the displayed value until the multimeter indicates the desired minimum output. This is typically 4 mA but this level can be adjusted from 0mA to 20mA.
6. Press the ENTER key to select the OUTPUT 1 SPAN mode. If OUTPUT 2 is required, continue pressing the ENTER key until OUTPUT 2 SPAN is displayed.
7. Using the arrow keys as explained in step 5, adjust the output to read 20mA on the multimeter. This output level can be adjusted from the minimum output setting up to 20mA if another range is required.
8. Press the SETUP key to save the calibration values and exit the calibration routine.

Process Calculations

Oxygen Process Control

Oxygen:

$$\%O_2 = \frac{20.95}{e^{(E/0.0215 \cdot T_k)}}$$

Where:

E = probe millivolts + mv offset, T_k = probe temperature in degrees Kelvin.
20.95 is the %O₂ in air.

An exponent setting of 2 will display percent oxygen. An exponent setting of 6 will display ppm oxygen levels. If the display is showing 'hhhh' then decrease the exponent value until a reading is obtained. If the reading is 0000 or 'LLLL' then increase the exponent value until a reading is obtained.

Refer to the oxygen charts at the end of this manual to determine which exponent setting is best for the signal levels and temperature in your process.

Versapro Monitor Mode

The Versapro is programmed to accept new operation code through a special key sequence. This mode allows the users to download an updated version of the firmware using a RS232 to RS485 converter and the popular Windows™ program HyperTerminal™. The user can also change the instrument's process function by loading different versions of the firmware.

Prepare of the download

Make sure you have recorded all the operational parameters of the instrument before you change the firmware. These parameters will include the thermocouple type, alarm functions, and probe care settings. For the controller version of the Versapro this will also include control and PID settings as well. Note the instrument calibration settings for the two analog output channels by going into the SETUP mode, selecting CAL OUT – Yes and recording the offset and span values shown for each channel. Advance to the each parameter by pressing the <Enter> key. Press <Setup> to return to the process mode.

The instrument to be programmed should be taken off-line since it has to go through a reset to accept the new program.

How to Connect

The Versapro has a RS485 half-duplex port located on terminals TB-B 13 and 14, where 13 is the +RS485 connection and 14 is the –RS485 connection.

Insure your converter is plugged into the serial port of your computer. Insure that your converter is configured as a half-duplex (two wire) output and not as a full-duplex (four wire) output.

Apply power to the instrument and observe that it is operating in normal process mode where the process name is displayed in the center LCD display.

NOTE

Your version of HyperTerminal may be different then the steps outlined in this procedure. The basic information provide here will apply to any configuration. Accept the setup defaults if you are not sure about a specific feature that is not addressed here.

When HyperTerminal starts up it asks for a name of a new connection. Enter a name that you can associate with the Versapro setup.

The 'Connect To' window will then appear.

Marathon Sensors Inc.

Make the following selections in the Connect To window;

Connect using: (select the comm port the RS485 is connected to)

Press the 'OK' button.

In the 'Port Settings' window that appears next, make the following selections;

Bits per second: 19200
Data bits: 7
Parity: EVEN
Stop bits: 1
Flow control: Hardware

Select the File \ Properties \ Settings tabs and make the following selections;

Select the 'Terminal Keys' button
Select the 'Ctrl+H' button
Set 'Emulation' to ANSI
Set 'Telnet terminal ID' to ANSI
Set 'Backscroll buffer lines' to 500

Click on the ASCII Setup... button;

Select the 'Echo typed characters locally' option
Set 'Line delay' to 25 msec
Set 'Character delay' to 0 msec

Click on the 'OK' button to escape the Connections window.

HyperTerminal will now be connected to the comms port waiting for serial data from the Versapro.

Start the download

At the Versapro press and hold the <REM> and <Enter> keys. Hold these keys until the center display changes to "MONITOR MODE", (about 5 seconds). The instrument will send a prompt to the HyperTerminal screen that should look like figure 5.




Figure 5 Initial Prompt Screen

At the '>' prompt type the character 'P' and press the Enter key. The instrument will return the response;

```
FLASH Erased  
Send New S19 File  
>_
```

Select the Transfer tab on the HyperTerminal task bar and then select 'Send Text File...' from the drop down list. Use the browser to select the Versapro program file with the .txt file extension. Click the 'Open' button.

The screen should show a line of changing numbers or a single line for streaming characters. This process will continue for a few minutes. Do not interrupt this process or switch to another application that may interfere with the data transmission.

At the end of the data transmission the instrument will send the prompt;

```
FLASH Programmed  
>
```

as shown if figure 6.




Figure 6 Flash Programmed Prompt

At the > prompt, type in the character 'L' and press the Enter key. This command will tell the instrument to load the RAM from the FLASH memory that has just been programmed.

A series of character lines will print down the screen followed by another prompt. At the prompt, type in the character 'K' and press Enter. This command will tell the instrument to load the EPROM from the RAM image that has just been programmed.

The screen will advance one line and display the prompt. At the prompt, type in the character 'X' and press Enter. The 'X' command causes the instrument to exit monitor mode, reset, and return to operation mode. This sequence is shown in figure 7.




Figure 7 Exit Command

Check the instrument parameter settings and verify the input and output calibration settings.

What if an error occurs

The instrument has a series of tests it does while it is receiving the program data, when it loads the RAM, and when it loads the EPROM. If you see a check sum error or reset prompts following the 'P' command download, check the connections between the instrument to the converter, and the converter to the computer. Also check the settings in HyperTerminal. Most of these types of problems are the result of slow transmission speeds in the comm port or a faulty converter. Downloading from another computer may also resolve this problem.

If you receive check sum errors following the 'L' or 'K' commands, retry these commands.

Problems loading the instrument memory usually result if HyperTerminal has locked up, the serial port buffer on the computer has been overrun, or the program file has been sent to the instrument before the 'P' command was typed in. If the instrument is turned off and on again quickly following this fault it will appear to be locked up. Power to the instrument should be turned off for at least one minute to allow the flash to recover. Shut down HyperTerminal and then restart it. Turn on the instrument. It can come up in one of two modes depending on where the transfer fault occurred. If it comes up in the process mode, press and hold the REM and Enter keys until the Marathon prompt appears on the HyperTerminal screen. You can test the communications link by typing a 'S' or a 'D' and then pressing the Enter key on the computer keyboard. The instrument will respond with status information or a memory block dump. Proceed with the program download as described in the previous procedure.

Marathon Sensors Inc.

If the LCD screen is blank but you get the Marathon prompt on HyperTerminal then proceed by typing 'P' then pressing the Enter key on the computer keyboard. The 'Send file' prompt should then be written to the HyperTerminal screen. Proceed with the remaining part of the procedure as described in the above procedure.

If this does not resolve errors during the RAM or EPROM procedures then the instrument memory maybe damaged. The instrument should be returned to Marathon Sensors, Inc. for testing and possible repair.

Technical Specification

Environmental ratings

Panel sealing: Instruments are intended to be panel mounted. The rating of panel sealing is IP64.

Operating temperature: 0 to 55°C. Ensure the enclosure provides adequate ventilation.

Relative humidity: 5 to 95%, non-condensing.

Atmosphere: The instrument is not suitable for use above 2000 meters or in explosive or corrosive atmospheres.

Equipment ratings

Supply voltage: 100 to 240Vac -15%, +10%, or optionally:

Supply frequency: 48 to 62Hz.

Power consumption: 15 Watts maximum.

BO/Verify Relay : Maximum: 264Vac, 1A resistive load. Minimum: 12Vdc, 100mA.

Control Triacs (isolated): Maximum: 280Vac, 1A resistive load.
Maximum on state voltage drop: 2.5V
Maximum leakage: 10uA
Isolation: 3750 VRMS

Alarm Triacs (isolated): Maximum: 280Vac, 1A resistive load.
Maximum on state voltage drop: 2.5V
Maximum leakage: 10uA
Isolation: 3750 VRMS

Over current protection: External over current protection devices are required that match the wiring of the installation. A minimum of 0.5mm² or 16awg wire is recommended. A Suitable fuse for the instrument circuit would be FNQ-R Class CC time-lag type fuses. The instrument power supply is protected by an internal 3.15A time lag fuse. Each alarm/control circuit is protected by an internal 1.0A time lag fuse.

Low level I/O: All input and output connections and probe relays are intended for low level signals less than 5VDC.

DC output (Isolated): 0 to 20mA (650Ω max), 0 to 10V (using a 500Ω dropping resistor).

Fixed digital inputs: Contact closure. (Non isolated.)

DC or PV input: As main input plus 0-1.6Vdc, Impedance, >100MΩ. (Isolated.)

Digital Comms: EIA-232, 2-wire EIA-485 or 4-wire EIA-485 (All isolated).

General

Thermocouple input Type B, K, R, and S accuracy after linearization +/- 1 deg F

Millivolt input 0 to 2000 millivolts +/- 0.1 millivolt

Marathon Sensors Inc.

Cold junction compensation	0 to 60°C +/- 1 deg F
Calibration accuracy:	The greater of ±0.2% of reading, ±1 LSD or ±1°C.
Isolation	1000V DC/AC
	Power input to signal inputs
	Power input to communications
Calculations	Percent carbon 0 – 2.55% (no CO compensation)
	Dewpoint -99 – 212 °F (no hydrogen compensation)
	Percent oxygen. 0 – 25.0%
	(Small oxygen concentrations can be measured by changing the exponent setting.)
Accuracy	+/- 1% of LSD of process value.
Probe Care	Probe verification and impedance for oxygen probes.
Communications port	RS-485 Half Duplex Only
Protocol	10Pro, MMI block transfer, or Modbus RTU
Baud rates	1200, 2400, 4800, 9600, 19.2K, or 38.4K
Parity	Even or None
Alarm Type (both Alarm 1 and 2)	
	High Limit Temp
	Low Limit Temp
	Input Fault (mV or Thermocouple)
	Impedance or Verification fault

Electrical safety (approval pending)

Standards:	EN 61010, Installation category II, pollution degree 2.
Installation category II:	Voltage transients on any mains power connected to the instrument must not exceed 2.0 kV.
Pollution degree 2:	Conductive pollution must be excluded from the cabinet in which the instrument is mounted.

Environmental Conditions

Operating Temperature	-20 °C to 65 °C (-4 to 176 F)
Storage Temperature	-40 °C to 85 °C (-40 to 185 F)
Operating and Storage Humidity	85% max relative humidity, noncondensing, from -20 to 65°C

Electromagnetic Compatibility

Immunity

Electrostatic discharge	EN 61000-4-2	Level 2: ±8 kV air Level 2: ±4 kV contact
Electromagnetic RF fields	EN 61000-4-3	Level 3: 10 V/m

Marathon Sensors Inc.

Fast Transients	EN 61000-4-4	80 MHz – 1000 MHz Level 3: ± 1 kV I/O Level 3: ± 2 kV power
RF conducted interference	EN 61000-4-6	Level 3: 10 V/rms 150 KHz – 80 MHz
Power Freq Magnetic Fields	EN 61000-4-8	30 A/m, x y z planes
Surge	EN 61000-4-5	± 1 kV L-L, ± 2 kV L-PE 5 / min at 0°, 90°, 270°
Voltage Variations	EN 61000-4-11	70% of operating voltage 0.5 cycles/10ms

Emissions

RF Emissions	CSIPR Class B
Conducted Emissions	CISPR Class B
Harmonic Current Emissions	EN 61000-3-2
Voltage Fluctuation	EN 61000-3-3

Note: Specifications may change without notification.

Marathon Sensors Inc.

Oxygen Chart

Deg C	1125	1150	1175	1200	1225	1250	1275	1300
Deg F	2057	2102	2147	2192	2237	2282	2327	2372
MV								
0	20.95%	20.95%	20.95%	20.95%	20.95%	20.95%	20.95%	20.95%
5	17.74%	17.79%	17.84%	17.89%	17.94%	17.98%	18.03%	18.07%
10	15.02%	15.11%	15.19%	15.28%	15.36%	15.44%	15.51%	15.59%
15	12.72%	12.83%	12.94%	13.05%	13.15%	13.25%	13.35%	13.45%
20	10.77%	10.90%	11.02%	11.14%	11.26%	11.37%	11.49%	11.60%
25	9.12%	9.25%	9.39%	9.51%	9.64%	9.76%	9.89%	10.00%
30	7.72%	7.86%	7.99%	8.13%	8.25%	8.38%	8.51%	8.63%
35	6.54%	6.67%	6.81%	6.94%	7.07%	7.19%	7.32%	7.44%
40	5.54%	5.67%	5.80%	5.93%	6.05%	6.18%	6.30%	6.42%
45	4.69%	4.81%	4.94%	5.06%	5.18%	5.30%	5.42%	5.54%
50	3.97%	4.09%	4.20%	4.32%	4.44%	4.55%	4.66%	4.78%
55	3.36%	3.47%	3.58%	3.69%	3.80%	3.91%	4.01%	4.12%
60	2.85%	2.95%	3.05%	3.15%	3.25%	3.35%	3.45%	3.55%
65	2.41%	2.50%	2.60%	2.69%	2.78%	2.88%	2.97%	3.07%
70	2.04%	2.13%	2.21%	2.30%	2.38%	2.47%	2.56%	2.64%
75	1.73%	1.81%	1.88%	1.96%	2.04%	2.12%	2.20%	2.28%
80	1.46%	1.53%	1.60%	1.68%	1.75%	1.82%	1.89%	1.97%
85	1.24%	1.30%	1.37%	1.43%	1.50%	1.56%	1.63%	1.70%
90	1.05%	1.11%	1.16%	1.22%	1.28%	1.34%	1.40%	1.46%
95	0.89%	0.94%	0.99%	1.04%	1.10%	1.15%	1.21%	1.26%
100	0.75%	0.80%	0.84%	0.89%	0.94%	0.99%	1.04%	1.09%
105	0.64%	0.68%	0.72%	0.76%	0.80%	0.85%	0.89%	0.94%
110	0.54%	0.58%	0.61%	0.65%	0.69%	0.73%	0.77%	0.81%
115	0.46%	0.49%	0.52%	0.56%	0.59%	0.63%	0.66%	0.70%
120	0.39%	0.41%	0.44%	0.47%	0.50%	0.54%	0.57%	0.60%
125	0.33%	0.35%	0.38%	0.40%	0.43%	0.46%	0.49%	0.52%
130	0.28%	0.30%	0.32%	0.35%	0.37%	0.40%	0.42%	0.45%
135	0.23%	0.25%	0.27%	0.30%	0.32%	0.34%	0.36%	0.39%
140	0.20%	0.22%	0.23%	0.25%	0.27%	0.29%	0.31%	0.33%
145	0.17%	0.18%	0.20%	0.22%	0.23%	0.25%	0.27%	0.29%
150	0.14%	0.16%	0.17%	0.18%	0.20%	0.21%	0.23%	0.25%
155	0.12%	0.13%	0.14%	0.16%	0.17%	0.18%	0.20%	0.21%
160	0.10%	0.11%	0.12%	0.13%	0.15%	0.16%	0.17%	0.18%
165	0.09%	0.10%	0.10%	0.11%	0.12%	0.14%	0.15%	0.16%
170	0.07%	0.08%	0.09%	0.10%	0.11%	0.12%	0.13%	0.14%
175	0.06%	0.07%	0.08%	0.08%	0.09%	0.10%	0.11%	0.12%
180	0.05%	0.06%	0.06%	0.07%	0.08%	0.09%	0.09%	0.10%
185	0.04%	0.05%	0.06%	0.06%	0.07%	0.07%	0.08%	0.09%
190	0.04%	0.04%	0.05%	0.05%	0.06%	0.06%	0.07%	0.08%
195	0.03%	0.04%	0.04%	0.04%	0.05%	0.05%	0.06%	0.07%
200	0.03%	0.03%	0.03%	0.04%	0.04%	0.05%	0.05%	0.06%

Marathon Sensors Inc.

Deg C	1125	1150	1175	1200	1225	1250	1275	1300
Deg F	2057	2102	2147	2192	2237	2282	2327	2372
MV								
205	2.29E-04	2.58E-04	2.90E-04	3.24E-04	3.61E-04	4.00E-04	4.43E-04	4.89E-04
210	1.94E-04	2.19E-04	2.47E-04	2.76E-04	3.09E-04	3.44E-04	3.81E-04	4.21E-04
215	1.64E-04	1.86E-04	2.10E-04	2.36E-04	2.64E-04	2.95E-04	3.28E-04	3.64E-04
220	1.39E-04	1.58E-04	1.79E-04	2.02E-04	2.26E-04	2.53E-04	2.82E-04	3.14E-04
225	1.18E-04	1.34E-04	1.52E-04	1.72E-04	1.94E-04	2.17E-04	2.43E-04	2.70E-04
230	9.96E-05	1.14E-04	1.30E-04	1.47E-04	1.66E-04	1.87E-04	2.09E-04	2.33E-04
235	8.43E-05	9.68E-05	1.10E-04	1.26E-04	1.42E-04	1.60E-04	1.80E-04	2.01E-04
240	7.14E-05	8.22E-05	9.41E-05	1.07E-04	1.22E-04	1.38E-04	1.55E-04	1.74E-04
245	6.05E-05	6.98E-05	8.01E-05	9.16E-05	1.04E-04	1.18E-04	1.33E-04	1.50E-04
250	5.12E-05	5.93E-05	6.82E-05	7.82E-05	8.92E-05	1.01E-04	1.15E-04	1.29E-04
255	4.34E-05	5.03E-05	5.81E-05	6.68E-05	7.64E-05	8.70E-05	9.86E-05	1.11E-04
260	3.67E-05	4.27E-05	4.95E-05	5.70E-05	6.54E-05	7.47E-05	8.49E-05	9.61E-05
265	3.11E-05	3.63E-05	4.21E-05	4.87E-05	5.60E-05	6.41E-05	7.30E-05	8.29E-05
270	2.63E-05	3.08E-05	3.59E-05	4.16E-05	4.79E-05	5.50E-05	6.29E-05	7.15E-05
275	2.23E-05	2.62E-05	3.06E-05	3.55E-05	4.11E-05	4.72E-05	5.41E-05	6.17E-05
280	1.89E-05	2.22E-05	2.60E-05	3.03E-05	3.51E-05	4.05E-05	4.65E-05	5.32E-05
285	1.60E-05	1.89E-05	2.22E-05	2.59E-05	3.01E-05	3.48E-05	4.00E-05	4.59E-05
290	1.35E-05	1.60E-05	1.89E-05	2.21E-05	2.58E-05	2.99E-05	3.45E-05	3.96E-05
295	1.15E-05	1.36E-05	1.61E-05	1.89E-05	2.21E-05	2.56E-05	2.97E-05	3.41E-05
300	9.70E-06	1.16E-05	1.37E-05	1.61E-05	1.89E-05	2.20E-05	2.55E-05	2.95E-05
305	8.22E-06	9.82E-06	1.17E-05	1.38E-05	1.62E-05	1.89E-05	2.20E-05	2.54E-05
310	6.96E-06	8.34E-06	9.93E-06	1.18E-05	1.38E-05	1.62E-05	1.89E-05	2.19E-05
315	5.89E-06	7.08E-06	8.46E-06	1.00E-05	1.19E-05	1.39E-05	1.63E-05	1.89E-05
320	4.99E-06	6.01E-06	7.20E-06	8.58E-06	1.02E-05	1.20E-05	1.40E-05	1.63E-05
325	4.22E-06	5.11E-06	6.14E-06	7.32E-06	8.69E-06	1.03E-05	1.20E-05	1.41E-05
330	3.58E-06	4.34E-06	5.23E-06	6.26E-06	7.44E-06	8.81E-06	1.04E-05	1.21E-05
335	3.03E-06	3.68E-06	4.45E-06	5.34E-06	6.37E-06	7.56E-06	8.92E-06	1.05E-05
340	2.56E-06	3.13E-06	3.79E-06	4.56E-06	5.46E-06	6.49E-06	7.67E-06	9.03E-06
345	2.17E-06	2.66E-06	3.23E-06	3.90E-06	4.67E-06	5.57E-06	6.60E-06	7.79E-06
350	1.84E-06	2.26E-06	2.75E-06	3.33E-06	4.00E-06	4.78E-06	5.68E-06	6.72E-06
355	1.56E-06	1.92E-06	2.34E-06	2.84E-06	3.43E-06	4.10E-06	4.89E-06	5.79E-06
360	1.32E-06	1.63E-06	1.99E-06	2.43E-06	2.93E-06	3.52E-06	4.21E-06	5.00E-06
365	1.12E-06	1.38E-06	1.70E-06	2.07E-06	2.51E-06	3.02E-06	3.62E-06	4.31E-06
370	9.45E-07	1.17E-06	1.45E-06	1.77E-06	2.15E-06	2.60E-06	3.12E-06	3.72E-06
375	8.01E-07	9.97E-07	1.23E-06	1.51E-06	1.84E-06	2.23E-06	2.68E-06	3.21E-06
380	6.78E-07	8.46E-07	1.05E-06	1.29E-06	1.58E-06	1.91E-06	2.31E-06	2.77E-06
385	5.74E-07	7.19E-07	8.93E-07	1.10E-06	1.35E-06	1.64E-06	1.99E-06	2.39E-06
390	4.86E-07	6.10E-07	7.61E-07	9.41E-07	1.16E-06	1.41E-06	1.71E-06	2.06E-06
395	4.12E-07	5.18E-07	6.48E-07	8.03E-07	9.89E-07	1.21E-06	1.47E-06	1.78E-06
400	3.48E-07	4.40E-07	5.52E-07	6.86E-07	8.47E-07	1.04E-06	1.27E-06	1.53E-06
405	2.95E-07	3.74E-07	4.70E-07	5.86E-07	7.25E-07	8.92E-07	1.09E-06	1.32E-06

Marathon Sensors Inc.

Deg C	1125	1150	1175	1200	1225	1250	1275	1300
Deg F	2057	2102	2147	2192	2237	2282	2327	2372
MV								
410	2.50E-07	3.18E-07	4.00E-07	5.00E-07	6.21E-07	7.65E-07	9.37E-07	1.14E-06
415	2.12E-07	2.70E-07	3.41E-07	4.27E-07	5.32E-07	6.57E-07	8.06E-07	9.83E-07
420	1.79E-07	2.29E-07	2.90E-07	3.65E-07	4.55E-07	5.64E-07	6.94E-07	8.48E-07
425	1.52E-07	1.94E-07	2.47E-07	3.12E-07	3.90E-07	4.84E-07	5.97E-07	7.31E-07
430	1.28E-07	1.65E-07	2.11E-07	2.66E-07	3.34E-07	4.16E-07	5.14E-07	6.31E-07
435	1.09E-07	1.40E-07	1.79E-07	2.27E-07	2.86E-07	3.57E-07	4.42E-07	5.44E-07
440	9.21E-08	1.19E-07	1.53E-07	1.94E-07	2.45E-07	3.06E-07	3.80E-07	4.69E-07
445	7.80E-08	1.01E-07	1.30E-07	1.66E-07	2.10E-07	2.63E-07	3.27E-07	4.05E-07
450	6.60E-08	8.59E-08	1.11E-07	1.42E-07	1.79E-07	2.26E-07	2.82E-07	3.49E-07
455	5.59E-08	7.30E-08	9.43E-08	1.21E-07	1.54E-07	1.94E-07	2.42E-07	3.01E-07
460	4.74E-08	6.20E-08	8.03E-08	1.03E-07	1.32E-07	1.66E-07	2.09E-07	2.60E-07
465	4.01E-08	5.26E-08	6.84E-08	8.81E-08	1.13E-07	1.43E-07	1.79E-07	2.24E-07
470	3.40E-08	4.47E-08	5.83E-08	7.53E-08	9.64E-08	1.22E-07	1.54E-07	1.93E-07
475	2.87E-08	3.79E-08	4.96E-08	6.43E-08	8.25E-08	1.05E-07	1.33E-07	1.67E-07
480	2.43E-08	3.22E-08	4.23E-08	5.49E-08	7.07E-08	9.03E-08	1.14E-07	1.44E-07
485	2.06E-08	2.74E-08	3.60E-08	4.69E-08	6.05E-08	7.75E-08	9.84E-08	1.24E-07
490	1.75E-08	2.32E-08	3.06E-08	4.00E-08	5.18E-08	6.65E-08	8.47E-08	1.07E-07
495	1.48E-08	1.97E-08	2.61E-08	3.42E-08	4.44E-08	5.71E-08	7.29E-08	9.23E-08
500	1.25E-08	1.68E-08	2.22E-08	2.92E-08	3.80E-08	4.90E-08	6.27E-08	7.96E-08
505	1.06E-08	1.42E-08	1.89E-08	2.49E-08	3.25E-08	4.21E-08	5.40E-08	6.87E-08
510	8.97E-09	1.21E-08	1.61E-08	2.13E-08	2.78E-08	3.61E-08	4.64E-08	5.92E-08
515	7.60E-09	1.03E-08	1.37E-08	1.82E-08	2.38E-08	3.10E-08	4.00E-08	5.11E-08
520	6.43E-09	8.72E-09	1.17E-08	1.55E-08	2.04E-08	2.66E-08	3.44E-08	4.41E-08
525	5.45E-09	7.40E-09	9.96E-09	1.33E-08	1.75E-08	2.28E-08	2.96E-08	3.80E-08
530	4.61E-09	6.29E-09	8.48E-09	1.13E-08	1.50E-08	1.96E-08	2.55E-08	3.28E-08
535	3.91E-09	5.34E-09	7.22E-09	9.67E-09	1.28E-08	1.68E-08	2.19E-08	2.83E-08
540	3.31E-09	4.54E-09	6.15E-09	8.26E-09	1.10E-08	1.44E-08	1.89E-08	2.44E-08
545	2.80E-09	3.85E-09	5.24E-09	7.05E-09	9.39E-09	1.24E-08	1.62E-08	2.10E-08
550	2.37E-09	3.27E-09	4.46E-09	6.02E-09	8.04E-09	1.06E-08	1.40E-08	1.82E-08
555	2.01E-09	2.78E-09	3.80E-09	5.14E-09	6.89E-09	9.14E-09	1.20E-08	1.57E-08
560	1.70E-09	2.36E-09	3.24E-09	4.39E-09	5.90E-09	7.84E-09	1.03E-08	1.35E-08
565	1.44E-09	2.00E-09	2.76E-09	3.75E-09	5.05E-09	6.73E-09	8.90E-09	1.17E-08
570	1.22E-09	1.70E-09	2.35E-09	3.20E-09	4.32E-09	5.78E-09	7.66E-09	1.01E-08
575	1.03E-09	1.44E-09	2.00E-09	2.73E-09	3.70E-09	4.96E-09	6.59E-09	8.67E-09
580	8.74E-10	1.23E-09	1.70E-09	2.33E-09	3.17E-09	4.26E-09	5.67E-09	7.48E-09
585	7.40E-10	1.04E-09	1.45E-09	1.99E-09	2.71E-09	3.66E-09	4.88E-09	6.45E-09
590	6.27E-10	8.85E-10	1.23E-09	1.70E-09	2.32E-09	3.14E-09	4.20E-09	5.56E-09
595	5.31E-10	7.52E-10	1.05E-09	1.45E-09	1.99E-09	2.69E-09	3.61E-09	4.80E-09
600	4.49E-10	6.38E-10	8.95E-10	1.24E-09	1.70E-09	2.31E-09	3.11E-09	4.14E-09
605	3.81E-10	5.42E-10	7.63E-10	1.06E-09	1.46E-09	1.99E-09	2.68E-09	3.57E-09
610	3.22E-10	4.60E-10	6.49E-10	9.06E-10	1.25E-09	1.70E-09	2.30E-09	3.08E-09

Marathon Sensors Inc.

Deg C	1125	1150	1175	1200	1225	1250	1275	1300
Deg F	2057	2102	2147	2192	2237	2282	2327	2372
MV								
615	2.73E-10	3.91E-10	5.53E-10	7.73E-10	1.07E-09	1.46E-09	1.98E-09	2.66E-09
620	2.31E-10	3.32E-10	4.71E-10	6.60E-10	9.15E-10	1.26E-09	1.70E-09	2.29E-09
625	1.96E-10	2.82E-10	4.01E-10	5.64E-10	7.84E-10	1.08E-09	1.47E-09	1.98E-09
630	1.66E-10	2.39E-10	3.42E-10	4.82E-10	6.71E-10	9.25E-10	1.26E-09	1.71E-09
635	1.40E-10	2.03E-10	2.91E-10	4.11E-10	5.75E-10	7.94E-10	1.09E-09	1.47E-09
640	1.19E-10	1.73E-10	2.48E-10	3.51E-10	4.92E-10	6.82E-10	9.35E-10	1.27E-09
645	1.01E-10	1.47E-10	2.11E-10	3.00E-10	4.21E-10	5.85E-10	8.04E-10	1.09E-09
650	8.52E-11	1.25E-10	1.80E-10	2.56E-10	3.61E-10	5.02E-10	6.92E-10	9.44E-10
655	7.21E-11	1.06E-10	1.53E-10	2.19E-10	3.09E-10	4.31E-10	5.96E-10	8.14E-10
660	6.11E-11	8.98E-11	1.30E-10	1.87E-10	2.64E-10	3.70E-10	5.13E-10	7.02E-10
665	5.17E-11	7.63E-11	1.11E-10	1.59E-10	2.26E-10	3.18E-10	4.41E-10	6.06E-10
670	4.38E-11	6.48E-11	9.45E-11	1.36E-10	1.94E-10	2.73E-10	3.80E-10	5.23E-10
675	3.71E-11	5.50E-11	8.05E-11	1.16E-10	1.66E-10	2.34E-10	3.27E-10	4.51E-10
680	3.14E-11	4.67E-11	6.86E-11	9.93E-11	1.42E-10	2.01E-10	2.81E-10	3.89E-10
685	2.66E-11	3.97E-11	5.84E-11	8.48E-11	1.22E-10	1.73E-10	2.42E-10	3.35E-10
690	2.25E-11	3.37E-11	4.97E-11	7.24E-11	1.04E-10	1.48E-10	2.08E-10	2.89E-10
695	1.91E-11	2.86E-11	4.24E-11	6.19E-11	8.92E-11	1.27E-10	1.79E-10	2.50E-10
700	1.61E-11	2.43E-11	3.61E-11	5.28E-11	7.64E-11	1.09E-10	1.54E-10	2.15E-10
705	1.37E-11	2.06E-11	3.07E-11	4.51E-11	6.54E-11	9.37E-11	1.33E-10	1.86E-10
710	1.16E-11	1.75E-11	2.62E-11	3.85E-11	5.60E-11	8.04E-11	1.14E-10	1.60E-10
715	9.80E-12	1.49E-11	2.23E-11	3.29E-11	4.79E-11	6.90E-11	9.82E-11	1.38E-10
720	8.30E-12	1.26E-11	1.90E-11	2.81E-11	4.11E-11	5.92E-11	8.45E-11	1.19E-10
725	7.03E-12	1.07E-11	1.62E-11	2.40E-11	3.51E-11	5.09E-11	7.27E-11	1.03E-10
730	5.95E-12	9.12E-12	1.38E-11	2.05E-11	3.01E-11	4.37E-11	6.26E-11	8.87E-11
735	5.04E-12	7.74E-12	1.17E-11	1.75E-11	2.58E-11	3.75E-11	5.38E-11	7.65E-11
740	4.27E-12	6.57E-12	9.98E-12	1.49E-11	2.21E-11	3.22E-11	4.63E-11	6.60E-11
745	3.61E-12	5.58E-12	8.50E-12	1.28E-11	1.89E-11	2.76E-11	3.99E-11	5.69E-11
750	3.06E-12	4.74E-12	7.24E-12	1.09E-11	1.62E-11	2.37E-11	3.43E-11	4.91E-11
755	2.59E-12	4.03E-12	6.17E-12	9.30E-12	1.38E-11	2.03E-11	2.95E-11	4.23E-11
760	2.19E-12	3.42E-12	5.25E-12	7.95E-12	1.19E-11	1.75E-11	2.54E-11	3.65E-11
765	1.86E-12	2.90E-12	4.47E-12	6.79E-12	1.02E-11	1.50E-11	2.19E-11	3.15E-11
770	1.57E-12	2.47E-12	3.81E-12	5.79E-12	8.69E-12	1.29E-11	1.88E-11	2.72E-11
775	1.33E-12	2.09E-12	3.24E-12	4.95E-12	7.44E-12	1.10E-11	1.62E-11	2.34E-11
780	1.13E-12	1.78E-12	2.76E-12	4.23E-12	6.37E-12	9.48E-12	1.39E-11	2.02E-11
785	9.55E-13	1.51E-12	2.35E-12	3.61E-12	5.46E-12	8.14E-12	1.20E-11	1.74E-11
790	8.08E-13	1.28E-12	2.00E-12	3.08E-12	4.67E-12	6.99E-12	1.03E-11	1.50E-11
795	6.85E-13	1.09E-12	1.71E-12	2.63E-12	4.00E-12	6.00E-12	8.88E-12	1.30E-11
800	5.80E-13	9.25E-13	1.45E-12	2.25E-12	3.43E-12	5.15E-12	7.64E-12	1.12E-11
805	4.91E-13	7.86E-13	1.24E-12	1.92E-12	2.93E-12	4.42E-12	6.57E-12	9.65E-12
810	4.16E-13	6.67E-13	1.05E-12	1.64E-12	2.51E-12	3.79E-12	5.66E-12	8.33E-12
815	3.52E-13	5.67E-13	8.97E-13	1.40E-12	2.15E-12	3.26E-12	4.87E-12	7.18E-12

Marathon Sensors Inc.

Deg C	1125	1150	1175	1200	1225	1250	1275	1300
Deg F	2057	2102	2147	2192	2237	2282	2327	2372
MV								
820	2.98E-13	4.81E-13	7.64E-13	1.20E-12	1.84E-12	2.80E-12	4.19E-12	6.20E-12
825	2.52E-13	4.09E-13	6.51E-13	1.02E-12	1.58E-12	2.40E-12	3.60E-12	5.34E-12
830	2.14E-13	3.47E-13	5.54E-13	8.72E-13	1.35E-12	2.06E-12	3.10E-12	4.61E-12
835	1.81E-13	2.95E-13	4.72E-13	7.44E-13	1.16E-12	1.77E-12	2.67E-12	3.98E-12
840	1.53E-13	2.50E-13	4.02E-13	6.36E-13	9.89E-13	1.52E-12	2.30E-12	3.43E-12
845	1.30E-13	2.13E-13	3.42E-13	5.43E-13	8.47E-13	1.30E-12	1.98E-12	2.96E-12
850	1.10E-13	1.81E-13	2.92E-13	4.63E-13	7.25E-13	1.12E-12	1.70E-12	2.55E-12
855	9.30E-14	1.53E-13	2.48E-13	3.96E-13	6.21E-13	9.60E-13	1.46E-12	2.20E-12
860	7.88E-14	1.30E-13	2.12E-13	3.38E-13	5.32E-13	8.24E-13	1.26E-12	1.90E-12
865	6.67E-14	1.11E-13	1.80E-13	2.89E-13	4.55E-13	7.07E-13	1.08E-12	1.64E-12
870	5.65E-14	9.39E-14	1.53E-13	2.46E-13	3.90E-13	6.07E-13	9.33E-13	1.41E-12
875	4.78E-14	7.97E-14	1.31E-13	2.10E-13	3.34E-13	5.21E-13	8.03E-13	1.22E-12
880	4.05E-14	6.77E-14	1.11E-13	1.80E-13	2.86E-13	4.47E-13	6.91E-13	1.05E-12
885	3.43E-14	5.75E-14	9.48E-14	1.54E-13	2.45E-13	3.84E-13	5.94E-13	9.07E-13
890	2.90E-14	4.88E-14	8.07E-14	1.31E-13	2.10E-13	3.30E-13	5.11E-13	7.82E-13
895	2.46E-14	4.15E-14	6.87E-14	1.12E-13	1.79E-13	2.83E-13	4.40E-13	6.75E-13
900	2.08E-14	3.52E-14	5.85E-14	9.56E-14	1.54E-13	2.43E-13	3.79E-13	5.82E-13
905	1.76E-14	2.99E-14	4.98E-14	8.16E-14	1.32E-13	2.09E-13	3.26E-13	5.02E-13
910	1.49E-14	2.54E-14	4.25E-14	6.97E-14	1.13E-13	1.79E-13	2.80E-13	4.33E-13
915	1.26E-14	2.16E-14	3.62E-14	5.95E-14	9.64E-14	1.54E-13	2.41E-13	3.74E-13
920	1.07E-14	1.83E-14	3.08E-14	5.08E-14	8.25E-14	1.32E-13	2.08E-13	3.22E-13
925	9.06E-15	1.56E-14	2.62E-14	4.34E-14	7.07E-14	1.13E-13	1.79E-13	2.78E-13
930	7.67E-15	1.32E-14	2.23E-14	3.71E-14	6.05E-14	9.72E-14	1.54E-13	2.40E-13
935	6.50E-15	1.12E-14	1.90E-14	3.17E-14	5.18E-14	8.34E-14	1.32E-13	2.07E-13
940	5.50E-15	9.53E-15	1.62E-14	2.70E-14	4.44E-14	7.16E-14	1.14E-13	1.78E-13
945	4.66E-15	8.09E-15	1.38E-14	2.31E-14	3.80E-14	6.15E-14	9.80E-14	1.54E-13
950	3.95E-15	6.87E-15	1.17E-14	1.97E-14	3.25E-14	5.28E-14	8.43E-14	1.33E-13
955	3.34E-15	5.84E-15	1.00E-14	1.68E-14	2.78E-14	4.53E-14	7.26E-14	1.14E-13
960	2.83E-15	4.96E-15	8.52E-15	1.44E-14	2.38E-14	3.89E-14	6.24E-14	9.87E-14
965	2.40E-15	4.21E-15	7.26E-15	1.23E-14	2.04E-14	3.34E-14	5.37E-14	8.52E-14
970	2.03E-15	3.58E-15	6.18E-15	1.05E-14	1.75E-14	2.87E-14	4.62E-14	7.35E-14
975	1.72E-15	3.04E-15	5.26E-15	8.95E-15	1.50E-14	2.46E-14	3.98E-14	6.34E-14
980	1.45E-15	2.58E-15	4.48E-15	7.65E-15	1.28E-14	2.11E-14	3.42E-14	5.47E-14
985	1.23E-15	2.19E-15	3.82E-15	6.53E-15	1.10E-14	1.81E-14	2.95E-14	4.71E-14
990	1.04E-15	1.86E-15	3.25E-15	5.58E-15	9.39E-15	1.56E-14	2.54E-14	4.07E-14
995	8.83E-16	1.58E-15	2.77E-15	4.76E-15	8.04E-15	1.34E-14	2.18E-14	3.51E-14
1000	7.48E-16	1.34E-15	2.36E-15	4.07E-15	6.89E-15	1.15E-14	1.88E-14	3.03E-14
1005	6.33E-16	1.14E-15	2.01E-15	3.47E-15	5.90E-15	9.84E-15	1.62E-14	2.61E-14
1010	5.36E-16	9.67E-16	1.71E-15	2.97E-15	5.05E-15	8.45E-15	1.39E-14	2.25E-14
1015	4.54E-16	8.21E-16	1.46E-15	2.53E-15	4.32E-15	7.25E-15	1.20E-14	1.94E-14
1020	3.84E-16	6.98E-16	1.24E-15	2.16E-15	3.70E-15	6.22E-15	1.03E-14	1.68E-14

Marathon Sensors Inc.

Deg C	1125	1150	1175	1200	1225	1250	1275	1300
Deg F	2057	2102	2147	2192	2237	2282	2327	2372
MV								
1025	3.25E-16	5.92E-16	1.06E-15	1.85E-15	3.17E-15	5.34E-15	8.86E-15	1.44E-14
1030	2.76E-16	5.03E-16	9.00E-16	1.58E-15	2.71E-15	4.59E-15	7.62E-15	1.25E-14
1035	2.33E-16	4.27E-16	7.66E-16	1.35E-15	2.32E-15	3.94E-15	6.56E-15	1.08E-14
1040	1.98E-16	3.63E-16	6.53E-16	1.15E-15	1.99E-15	3.38E-15	5.64E-15	9.27E-15
1045	1.67E-16	3.08E-16	5.56E-16	9.82E-16	1.70E-15	2.90E-15	4.86E-15	8.00E-15
1050	1.42E-16	2.62E-16	4.73E-16	8.39E-16	1.46E-15	2.49E-15	4.18E-15	6.90E-15
1055	1.20E-16	2.22E-16	4.03E-16	7.16E-16	1.25E-15	2.14E-15	3.60E-15	5.95E-15
1060	1.02E-16	1.89E-16	3.43E-16	6.12E-16	1.07E-15	1.84E-15	3.09E-15	5.13E-15
1065	8.60E-17	1.60E-16	2.92E-16	5.22E-16	9.15E-16	1.58E-15	2.66E-15	4.43E-15
1070	7.28E-17	1.36E-16	2.49E-16	4.46E-16	7.84E-16	1.35E-15	2.29E-15	3.82E-15